

TARP REPAIR SYSTEM



Use:

The surface must be clean, dry and grease-free.

Clean dirt and oil over a large area from the defective spots with a clean cloth (TexRein, Art. No. 0899 810) and 1A Assembly and Part Cleaner Art. No. 0890 106 500.

Select a patch and remove the protective film. Adhere the patch onto the surface without folds, press it firmly into place and hit it using a rubber mallet on a firm surface, if necessary.

Attention! – The patch cannot be pulled off and corrected following application!

| Color | | Patch Kit32 pc.** Art. No. | Patch Kit500 x 210 mm*** Art. No. | P. Qty. |
|--------------------|---|-------------------------------|--------------------------------------|------------|
| Silver | ◆ | 161 0880 600 161 | 0880 800 161 | 1 |
| White | ◆ | 290 0880 600 290 | 0880 800 290 | 1 |
| Ivory | | 1014 0880 601 014 | | 1 |
| Zinc yellow | ◆ | 1018 0880 601 018 | 0880 801 018 | 1 |
| Broom yellow (DHL) | | 1032 0880 601 032 | | 1 |
| Pure orange | | 2004 0880 602 004 | | 1 |
| Deep orange | ◆ | 2011 0880 602 011 | | 1 |
| Fire red | ◆ | 3000 0880 603 000 | 0880 803 000 | 1 |
| Ultramarine blue | ◆ | 5002 0880 605 002 | 0880 805 002 | 1 |
| Light blue | ◆ | 5012 0880 605 012 | 0880 805 012 | 1 |
| Emerald green | ◆ | 6001 0880 606 001 | 0880 806 001 | 1 |
| Yellow green | | 6018 0880 606 018 | | 1 |
| Braungrau (NATO) | | 7013 0880 607 013 | | 1 |
| Light gray | ◆ | 7035 0880 607 035 | 0880 807 035 | 1 |
| Black | ◆ | 9005 0880 609 005 | 0880 809 005 | 1 |
| Assorted | | Content see | 0880 800 100 | 1 |

*All colors are similar to RAL; 161 and 290 are manufacturer specifications./ **Contents: 3 300 x 200 mm patches, 3 200 x 200 mm patches, 4 300 x 100 mm patches, 4 200 x 100 mm patches, 6 100 x 100 mm patches, 6 200 x 50 mm patches, 6 100 x 50 mm patches./ ***Contents:10 plasters of size 500 x 210 mm.

Mobile, self-adhesive repair system for defective truck tarps, tents, covers and much more.

Problem solution – Simple, long-lasting and mobile!

Simple, professional repair.

- Ready-to-use patches with high bonding strength.
- Fast application.
- Large choice of colors.

Can be used on the go.

- Fast, reliable repair of damaged areas at any time.

Cost-optimized.

- No need to visit a workshop.
- Repair times are considerably reduced.
- Unnecessary downtimes are decreased.
- No more recourse claims based on freight damage.

UV-resistant.

Resistant to washing brushes.

Areas of application:

Unique system for the repair of defective tarps on the road and in the repair shop. Holes, rips and tears can be repaired permanently in an uncomplicated manner at low cost. Can be used for truck tarps, event tents, impact and piste guards as well as box bodies, campers, ski boxes and much more

Note:

Application temperature: -15°C to +40°C,
Temperature-resistance: -40°C to +70°C.

Additional articles:

TexRein Cleaning Cloth

Art. No. 0899 810

P. Qty. 1

1A Assembly and Part Cleaner, 500 mL

Art. No. 0890 106 500

P. Qty. 1

Rubber Mallet

Art. No. 0715 734 08

P. Qty. 1

This information is only a recommendation based on our experience. Preliminary testing required! For further information, see the technical information leaflet.