

# WINDSHIELD WIPER OVERVIEW

 Make	 Model	 Year of manufacture	 Flat blade Art. No.	 Flat blade connection	 Standard Art. No.	 Spoiler Art. No.	 Rear Art. No.
<b>PEUGEOT</b>							
406 Coupe	[D8]	03.97-03.99				<b>0848 660 2</b>	
406 Coupe	[D9]	04.99-02.05				<b>0848 660 2</b>	
407 SW	[D2]	05.04-	<b>0848 470 2</b>				
Expert	[G9]	02.07\z→			<b>0848 770 1</b>		
Expert	[U64]	09.95\z→			<b>0848 770 1</b>		
Partner	[M4]	07.96-08.02	<b>0848 355 0</b>	Hooks	<b>0848 756 0</b>		
Partner	[M5]	09.02\z→	<b>0848 355 0</b>	Hooks	<b>0848 756 0</b>		
Ranch	[M4]	07.97\z→	<b>0848 355 0</b>	Hooks	<b>0848 756 0</b>		
<b>PORSCHE</b>							
Boxster	[986]	10.96-08.04				<b>0848 655 0</b>	
Boxster	[987]	09.04\z→				<b>0848 655 0</b>	
Cayenne	[9PA]	09.02-01.07	<b>0848 465 1</b>	SL			
Cayman S, Cayman	[987C]	11.05\z→				<b>0848 655 0</b>	
911	[996]	09.97-07.04				<b>0848 655 0</b>	
911	[996T/GT2/GT3]	03.99\z→				<b>0848 655 0</b>	
911	[997]	08.04\z→				<b>0848 655 0</b>	
911	[997 GT2, GT3]	03.06\z→				<b>0848 655 0</b>	
968		08.91-11.95			<b>0848 747 5</b>		
<b>PROTON</b>							
Persona	[C90 CC0; C90 CC1]	11.94\z→			<b>0848 750 1</b>		
Persona	[C90 CC0]	11.94-12.97	<b>0848 350 1</b>	Hooks			
<b>RENAULT</b>							
Clio I	[X57]	01.94-02.98	<b>0848 350 2</b>	Hooks	<b>0848 750 0</b>	<b>0848 650 0</b>	
Clio I	[X57]	06.90-03.96	<b>0848 345 0</b>	Hooks	<b>0848 745 0</b>	<b>0848 645 0</b>	<b>0848 940 1</b>
Clio II	[BB./CB./SB.]	03.98-10.07	<b>0848 353 2</b>	Hooks		<b>0848 753 1</b>	
Espace II	[J63]	01.91-09.96			<b>0848 760 3</b>		<b>0848 940 1</b>
Express, Extra, Rapid	[F40]	03.86-10.97	<b>0848 345 0</b>	Hooks	<b>0848 7450</b>	<b>0848 645 0</b>	<b>0848 940 1</b>
Kangoo	[FC./KC.]	10.97\z→	<b>0848 350 2</b>	Hooks	<b>0848 750 0</b>	<b>0848 650 0</b>	
Laguna I	[B56; 556]	01.94-02.01	<b>0848 360 0</b>	Hooks		<b>0848 660 4</b>	
Laguna I Grandtour	[A56]	09.99-02.01	<b>0848 360 0</b>	Hooks		<b>0848 660 4</b>	
Laguna I Grandtour	[K56]	02.95-02.01	<b>0848 360 0</b>	Hooks		<b>0848 660 4</b>	
Laguna I Grandtour	[S56]	02.95-02.01	<b>0848 360 0</b>	Hooks		<b>0848 660 4</b>	
Laguna II	[BG.]	03.01-09.07				<b>0848 660 3</b>	
Laguna II Grandtour	[KG.]	03.01-09.07				<b>0848 660 3</b>	
Logan	[KS./LS.]	07.04\z→	<b>0848 350 2</b>	Hooks	<b>0848 750 0</b>		
Megane I	[X64]	01.96-09.03	<b>0848 355 2</b>	Hooks	<b>0848 756 1</b>		
Megane II	[LM.]	09.02-01.06	<b>0848 360 0</b>	Hooks		<b>0848 660 4</b>	
Megane II		03.06\z→	<b>0848 360 0</b>	Hooks			
R 19	[X53]	06.89-12.01			<b>0848 750 0</b>	<b>0848 650 0</b>	
R 19 Cabrio	[X53]	06.89-12.95			<b>0848 750 0</b>	<b>0848 650 0</b>	
R 21	[L48]	03.86-12.94			<b>0848 745 0</b>	<b>0848 645 0</b>	
R 21 Fastback	[B48]	09.89-12.93			<b>0848 745 0</b>	<b>0848 645 0</b>	
R 21 Nevada	[K48]	06.86-12.95			<b>0848 745 0</b>	<b>0848 645 0</b>	
R 5		10.84-12.96	<b>0848 345 0</b>	Hooks	<b>0848 745 0</b>	<b>0848 645 0</b>	
Scenic		01.02\z→			<b>0848 760 1</b>		
Scenic I	[JA]	01.96\z→	<b>0848 357 6</b>	Hooks	<b>0848 760 1</b>		
Thalia II	[LB.]	10.99-10.07	<b>0848 353 2</b>	Hooks		<b>0848 753 1</b>	
<b>ROVER</b>							
25		02.00-05.05	<b>0848 345 0</b>	Hooks	<b>0848 745 0</b>	<b>0848 645 0</b>	
45		02.00-05.05	<b>0848 345 0</b>	Hooks	<b>0848 745 0</b>	<b>0848 645 0</b>	
75		01.99-05.05	<b>0848 355 0</b>	Hooks	<b>0848 756 0</b>	<b>0848 656 0</b>	
211		11.95-03.00	<b>0848 345 0</b>	Hooks			