

Installation Tapes

Notes on application

- The surfaces to be adhered must be dry and free of dust, grease and silicone.
- To ensure perfect adhesion, the tape must be sufficiently pressed to the material to be adhered.
- With sensitive surfaces and porous surfaces (e.g. wood, stone), please carry out preliminary tests.
- In cases where plastics containing softener additives are to be adhered, the softener can modify the adhesive coating. This impairs the strength of the adhesive.
- The installation tapes are only conditionally UV-resistant and should therefore be protected from direct sunlight.

Technical data

	Installation Tape universal	Installation Tape specialised
Adhesive basis	Rubber	Hotmelt, rubber basis
Carrier	PP film (white)	Rayon staple cloth (white)
Adhesive strength	20 N/25 mm	25 N/25 mm
Elongation at tear	35%	7%
Application temperature	+15°C to +30°C (applies for surface and tape)	
Thermal stability	-30°C to +80°C	-30°C to +90°C
Shelf life (at approx. +20°C and 50% humidity)	12 months	
UV resistance	conditional	
Moisture resistance	given	

With this information we want to advise you to the best of our knowledge based on our tests and experience. However, we shall assume no liability for the application results in individual cases due to the large number of applications and the storage and application conditions which lie outside the scope of our influence.

This also applies to the use of the non-binding technical and commercial Customer Service we provide. We always recommend that you conduct your own tests. We guarantee the consistent quality of our products. We reserve the right to make technical changes and carry out further development.