

## FUSE HOLDER



- Ideal for short circuit troubleshooting on electrical and electronic components.
- With 4 mm plug and socket  
→ Allows the use of 4 mm measuring cables.
- Rated voltage <50 V.

**Art. No. 0715 531 010**

P. Qty./Pair 1

**We recommend using reclosing circuit breakers – whereby ordinary fuses can also be used.**

## SILICONE Y-CABLES

- Length: approx. 250 mm.  
→ Plug and socket separately connectable to allow function to be measured in parallel in a closed line. Very useful for measurements on sensors.
- Rated voltage <50 V.



Fig.	Designation	Art. No.	P. Qty.
	Flat contact 4.8/0.5 Plug and socket, red	<b>0715 531 025</b>	1
	Flat contact 4.8/0.5 Plug and socket, black	<b>0715 531 026</b>	
	Flat contact 2.8/0.8 Plug and socket, red	<b>0715 531 027</b>	
	Flat contact 2.8/0.8 Plug and socket, black	<b>0715 531 028</b>	
	Flat contact 1.2 x 0.5 Plug and socket, red	<b>0715 531 029</b>	
	Flat contact 1.2 x 0.5 Plug and socket, black	<b>0715 531 030</b>	
	Flat contact 0.63 Plug and socket, red	<b>0715 531 031</b>	
	Flat contact 0.63 Plug and socket, black	<b>0715 531 032</b>	
	Round contact 2.5 Plug and socket, red	<b>0715 531 033</b>	
	Round contact 2.5 Plug and socket, black	<b>0715 531 034</b>	
	Round contact 1.5 Plug and socket, red	<b>0715 531 035</b>	
	Round contact 1.5 Plug and socket, black	<b>0715 531 036</b>	
	Round contact 1.0 Plug and socket, red	<b>0715 531 037</b>	
	Round contact 1.0 Plug and socket, black	<b>0715 531 038</b>	