

Ø°Ø°Ü²ÚÆ È²Øä°ð, 12 V

î Ýî »ëãŒ

Üî³ñ	Øá¹»é	ì áéî	ì ³î î	î »ë³î	²ñî Çîáóé	óÄ./ð³î
A	P21W	12	21W	BA15s	0720 732 1	10
B	PY21W	12	21W	BAU15s	0720 738 3	10
C	P21/5W	12	21/5W	BAY15d	0720 734 1	10
D	P21/5W	12	21/5W	BA15d	0720 731 11	10
E	P21/4W	12	21/4W	BAZ15d	0720 734 11	10
F	PY21/5W	12	21/5W	BAY15d	0720 738 31	10
G	W3W	12	3W	W2, 1 × 9, 5d	0720 761 1	10
H	W5W	12	5W	W2, 1 × 9, 5d	0720 762 1	10
I	-	12	15W	W2, 1 × 9, 5d	0720 763 11	10
J	W21W	12	21W	W3 × 16d	0720 763 1	10
K	W21/5W	12	21/5W	W3 × 16q	0720 763 2	10
L	R5W	12	5W	BA15s	0720 740 1	10
M	R10W	12	10W	BA15s	0720 741 1	10
N	C5W	12	5W	SV8, 5 - 8	0720 771 1	10
O	C10W	12	10W	SV8, 5 - 8	0720 773 51	10

²ñ. »É³ îÜ³ Ý, BñÇ³ 1³ ñÓÇ ³ ½1³ ÝB³ Ý³ ÛÇÝ, Ñ³ î³. Û³ é³ ÈáóŒ³ ÛÇÝ »ð Ñ»î »ðÇ Éáóðë»ñÇ É³ Úá»ñ

