

TIRE PRESSURE MONITORING SYSTEM VDO REPLACEMENT VALVE



Art. No.	0879 951 002
P.Qty.	10
Suitable for tire pressure sensor	SEL 90518384SEL 90518279
Schrader comparison number	43148-67
Material	ALL Alloy

TIRE PRESSURE MONITORING SYSTEM VDO REPLACEMENT VALVE



Art. No.	0879 951 003
P.Qty.	10
Material	ALL Alloy